

ACOUSTIC GUITAR, MANDOLIN AND BANJO REPAIR PRICE GUIDE

HIGH VALUE PROFESSIONAL INSTRUMENTS NOT UNDERTAKEN	
reduce height of action by reducing saddle and adjusting neck etc	£33
replace top nut	£33
replace bridge saddle (guitar and mandolin)	£33
replace bridge (banjo)	£22
replace machine heads and pegs (new strings will have to be fitted) PLUS PARTS	£32
glue split or broken parts (not an invisible repair) Subject to inspection	£50
replace banjo vellum. Subject to inspection	£70

Jim Beckett Musical instrument repairs

Tel: 023 8026 1645 Mobile: 07518 777875 E-mail: jimbeckettmusicrepair@talktalk.net

Copyright © 2010 Jim Beckett