

ACOUSTIC GUITAR, MANDOLIN AND BANJO REPAIR PRICE GUIDE

HIGH VALUE PROFESSIONAL QUALITY INSTRUMENTS NOT UNDERTAKEN	
reduce height of action by reducing saddle and adjusting neck etc	£35
replace top nut	£35
replace bridge saddle (guitar and mandolin)	£35
replace bridge (banjo)	£25
replace machine heads or pegs (new strings will have to be fitted) PLUS PARTS	£50
glue split or broken parts (not an invisible repair) Subject to inspection	£50
replace banjo vellum. Subject to inspection and quotation. MINIMUM COST	£80

Jim Beckett Musical instrument repairs

Tel: 023 8026 1645 Mobile: 07518 777875 E-mail: jimbeckettmusicrepair@talktalk.net

Copyright © 2008, 2009, 2010 & 2011 Jim Beckett