

**CORNET, TRUMPET, FLUGEL HORN AND TENOR HORN
SERVICE PRICE GUIDE (SEE FOOTNOTES)**

	1	2	3	4	5
Free up sticking or sluggish valves due to build up of deposits			x	x	x
free up sticking or sluggish valves due to damage or other uncertain cause		x			
free up stuck tuning slides (SEE FOOTNOTE)				x	x
fully dismantle and wash interior and exterior tubing			x	x	x
check condition of valve guides, springs, felts, water key corks and renew as necessary				x	x
polish silver plated instrument					x
wash and disinfect mouth piece			x	x	x
carry out a playing test			x	x	x
check for leaks (submerged water test)				x	x
SPECIAL SINGLE JOBS					
remove stuck mouth piece					
£3.50					
free up stuck tuning slide (SEE FOOTNOTE) first slide					
£28.00					
free up stuck tuning slide (SEE FOOTNOTE) each additional slide					
£10.00					
re-shape creased / dented bell (Not an invisible repair)					
£32.00					
re-shape dented tubing (Not an invisible repair) per area					
£60.00					
soft solder mouth-pipe, tuning slide or other sleeve joint. Per area					
£40.00					
soft solder stay or finger hook or water key bracket.					
£32.00					
FOOTNOTES					
stuck tuning slides					
Sometimes these come out fairly easily, other times they do not. On some instruments, especially Yamaha, the tuning slide may have to be cut out and another obtained and fitted. Customers will be notified if this is the case. In any event a charge will be made for trying.					
Operations indicated in columns are carried out in the following services					
1 Service not available	1				
2 Seek an instrument examination and quotation		2			
3 Short service			3		
£65.00					
4 Full service (EXCLUDING PARTS)				4	
£125.00					
5 Full service on silver plated instrument (EXCLUDING PARTS)					5
£155.00					

Jim Beckett musical instrument repairs
Tel: 023 8026 1645 Mobile: 07518 777875 E-mail: jimbeckettmusicrepair@talkytalk.net
Copyright © 2010 Jim Beckett